

****Note****

- 1) All 320A Sockets Must Have A By-Pass Lever
- 2) Socket May Be Used For 120/208Y Service If So, Fifth Terminal Meter Jaw Is Required In 9 O'Clock Position
- 3) Walton EMC May Install Only 1(One) Run Of Service Conductor

